# HARYANA URBAN DEVELOPMENT AUTHORITY PANCHKULA

#### (INSPECTION REPORT OF SECTOR: 31, GURGAON)

1.	Name & Designation of the Inspecting Officer		Yashendra Singh, HCS Estate Officer-II, HUDA, Ggn.	
2.	Date of Inspection		07-07-200	
3.	Sector/Urban Estate		Sector-31	
4.	Sector floated in year		1988	
5.	Possession offered in year(s)		25-02-1992	
6.	Plot details:			
a)	Category of Plot	Total Plots carved out.	Allotted	Unallotted
2	2. Residential	1350	1350	nil
3	3. Commercial	218	93	125
4	1. Industrial	Nil	Nil	Nil
5	5. Institutional	Nil	Nil	Nil
6	S. School	4	4	Nil
7	7. Religious	3	3	Nil
8	3. Social & Charitable	3	3	Nil
	). Others Nursing Home/Clinic	4	4	Nil
b) Whether above details tally with the details given on the official website in respect of this Sector? In case of discrepancy, details thereof			Yes	
7.	Drawing No.(s)/Date (s) vide which demarcation plans have been approved.		DTP(G) 27	76/92 dt. 12-02-92
8.	No. of plots/sites in respect of which litigation is going on. Full details may be given by means of Annexures.		Nil	

9.	Whether registered RWA exists. If yes, names of President and General Secretary.	Yes President: Col. Man Singh Gen. Secy: Comdt. P. S. Dabas
10.	Whether advance notice given and RWA representative present at the time of inspection.	Yes
11.	Condition of major infrastructure:	
(	i) ROADS:	
	a) Last special repair done and when due next ime.	Main Roads 2008 January – Special repair done (except 10% work) New Estimate under process.
	(b) General condition i.e. whether potholes exist or not.	
(	ii) WATER SUPPLY	
	(a) Number of Tubewells/ Pumping Stations.	1- Pumping Stations 3- Tube-wells 2- Boosters
1	. Average hours for which water supplied during last calendar month.	12 hours
	(c) Number of complaints received & redressed.	No complaint received as told by RWA & JE.
2	2. Address of the Complaint Centre and Phone No.	O/o SDE (Civil) Booth 10-11-12, Sector-31 No Telephone
1	. <u>SEWERAGE:</u>	
1	. Whether there are any blockages or any temporary pumping is being done or it is in perfect condition?	Master Sewerage Blocked. A pumping Station has been established which has motor & generator
2	When was preventive cleaning of sewer done?	Done time to time.
(	i) <u>STORM WATER:</u>	
	Whether Storm Water Services have been laid on all roads in the Sector? If not, then details thereof.	Storm water services not connected to master sewer. Master storm water does not exist.

(ii) <u>PARKS:</u>	
(a) Total number of Parks & area of each park.	10 in number 1. 3276 sqm. 2. 5372.78 sqm. 3. 1000 sqm. 4. Not provided by Horticulture Wing. 5. 880 sqm. 6. 3500 sqm. 7. 2850 sqm. 8.2045 sqm. 9. 3432 sqm. 10. 855 sqm.
(b) Handed over to RWAs for maintenance & their general condition.	Yes Good
© Maintained by HUDA and their general condition.	Not maintained by HUDA.
(iii) <u>STREET LIGHTS:</u>	
(a) Total number of Points	620 (520 street light + 100 sodium) 40% functional.
(b) Number of switching on/off points.	8
a. Method of switching on/off. Whether through contractor or employees of HUDA?	HUDA Employees
(d)Total amount of last electricity bill due and paid.	Rs. 17,378/- Paid upto April, 2008.
(iv) <u>SINEAGES:</u>	
Whether adequate Sineages indicting important landmarks in the Sector including plot numbers are in proper condition?	It is not adequate. Hoswever, tender has been allotted
11. Cleanliness:	
2. Number of Sweepers to be deployed by Contractors.	30
Number of Sweepers actually deployed.	30
(c) Method of checking their attendance. b. Method of collection of garbage and its	JE (Survey) & RWA. Through Rehri & Tractor
disposal.	Trolleys.

AO I Whathan are a second as a second as		In Hausing Doord area in the	
12.	Whether any encroachment – permanent or temporary exists? If yes, details thereof.		In Housing Board area in the form of ramps.
13.	Action taken for removal of encroachments.		Removed by survey wing from time to time.
14.	Details of unplanned areas in the Sector in following format:		
	Location	Area	Purpose for which it can be used.
Nil		Nil	Nil
15.	15. Beautification of Entries into Sector.		
1	Number of major entri	es into the Sector.	4 (one in litigation)
(b) How many of them are beautified?			Average.
16.	16. Community Buildings constructed by HUDA.		Community Centre
17.	Are these Community Buildings maintained by HUDA or transferred to different Departments/NGOs?		By RWA with the help of HUDA
18.	'		Not maintained by HUDA
19.	Whether Assessment Form filled up by RWA is enclosed or Not?		Yes
20.			2 hours
21.	Names of the officials who accompanied the EO during Inspection.		
(a) JE (Civil)			Shri Sohan Singh Raghav
(b) JE (Electrical)			Shri R. S. Malik
(c) JE (Horti.)			Shri Narender Singh
(d) JE (Estate Office)			Shri H. S. Jakhar
22.	22. Overall Assessment:		Yes. To a large extent
	Whether physical condition and maintenance of Sector helps in improving image of HUDA?		

## ASSESSMENT FORM TO BE FILLED UP BY RESIDENT WELFARE ASSOCIATION.

### **DATE OF INSPECTION** : 07-07-2008

1.	Name of RWA.	Sector-31
2.	Registration number, Act under which registered & date of registration.	RWA Regn. No. 180
3.	Name & Address, Mobile No., e-mail	Col. Man Singh
	address of the President and General	Tel.9871016593/2580811
	Secretary.	Comdt. P.S.Dabas
		9350261310/2380415
		# 244/31, Gurgaon
4.	Assessment out of 10 marks in respect	
	of:	
(a)	JE (Civil) for water supply, sewerage & storm water.	10
(b)	JE (Electrical) for Street light.	08
(c)	JE (Horti.) for Parks	10
(d)	JE (Estate Office) for cleanliness, maintenance of open spaces, sineages, prevention & removal of encroachments.	10

Signature of President/Gen.Secy./ Authorised Representative of

RWA.

### TO BE FILED UP BY THE INSPECTING OFFICER:

Whether the Inspecting Officer	I agree.
agrees with the above Assessment	
done by RWA? If not, then what is	
his Assessment and reasons	
therefor.	

the

Name & Signature of Inspecting Officer